Date:

Thursday, 5/3/2007 11:36:02 AM

User

Kim Johnston

**Process Sheet** 

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number** 

: 32185

P.O. Number

: 12816

This Issue

:NIA : 5/3/2007

Type

: NC Prsht Rev. : NA First Issue

: 32182

Previous Run

Checked & Approved By

Comment

Written By

New Issue 07-04-05 JLM : Est Rev:A

: LANDING GEAR

**Drawing Name** 

: 412 X-TUBE INST,LOW NARROW FWD

Part Number

**Drawing Number** 

Project Number **Drawing Revision** 

Material **Due Date**  : D412664105

: D412-664 UNDER : N/A

UR C

:NK : 8/6/2007

07,06.14

Qty:

1 Um:

Each

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0

2.0

DOCUMENT CONTROL

Comment: DOCUMENT CONTROL

Photocopy bluefile and create labels as per PPP D412-664-105 CHG001

PACKAGING 1

PACKAGING RESOURCE



Comment: PACKAGING RESOURCE #1

Pick Packing Kit

3.0

Crosstube 412 Low



Comment: Qty.:

1.0000 Each(s)/Unit

Total:

1.0000 Each(s)

Crosstube 412 Low

Batch:

4.0





4.0000 Each(s)/Unit

Total:

4.0000 Each(s)

BOLT

Comment: Qty.: Bolt

Batch:

11/0 344

5.0

AN636A



Comment: Qty.:

4.0000 Each(s)/Unit

Total:

4.0000 Each(s)

Bolt Batch:

M/02929

| Dail Acidsbace Liu | <b>Dart</b> | Aeros | pace | Ltd |
|--------------------|-------------|-------|------|-----|
|--------------------|-------------|-------|------|-----|

| <b>W</b> /O: |      | WORK ORDER CHANGES |    |      |     |                               |                          |
|--------------|------|--------------------|----|------|-----|-------------------------------|--------------------------|
| DATE         | STEP | PROCEDURE CHANGE   | Ву | Date | Qty | Approval Chief Eng / Prod Mgr | Approval<br>QC Inspector |
|              |      |                    |    |      |     |                               |                          |
|              |      |                    | !  |      |     |                               |                          |
|              |      |                    |    |      |     |                               |                          |
|              |      |                    |    |      |     |                               |                          |
|              |      |                    |    |      |     |                               |                          |
|              |      |                    |    |      |     |                               | L                        |

| Part No: | PAR #: | Fault Category: | NCR: Yes No DQA: | Date: SHOP R |
|----------|--------|-----------------|------------------|--------------|
|          |        |                 | QA: N/C Closed:  | Date:        |

| NCR:       |      |                   | WORK ORDE            | ER NON-CONFORMAN             | CE (NCR)       |              |                       |                          |
|------------|------|-------------------|----------------------|------------------------------|----------------|--------------|-----------------------|--------------------------|
|            |      | Description of NC |                      | Corrective Action Section B  | 3              | Verification | Annroval              | Annroyal                 |
| DATE       | STEP | Section A         | Initial<br>Chief Eng | Action Description Chief Eng | Sign &<br>Date | Section C    | Approval<br>Chief Eng | Approval<br>QC Inspector |
|            |      |                   |                      |                              |                |              |                       |                          |
|            |      |                   |                      |                              |                |              |                       |                          |
|            |      |                   |                      |                              |                |              |                       |                          |
|            |      |                   |                      |                              |                |              |                       |                          |
|            |      |                   |                      |                              |                |              |                       |                          |
| , <u>-</u> |      |                   |                      |                              |                |              |                       |                          |
|            |      |                   |                      |                              |                |              |                       |                          |
|            |      | ·                 |                      |                              |                |              |                       |                          |
|            |      |                   |                      |                              |                |              |                       |                          |

NOTE: Date & initial all entries

Ďate: User:

Thursday, 5/3/2007 11:36:02 AM

Kim Johnston

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 412 X-TUBE INST, LOW NARROW FWD

Job Number: 32185

Part Number: D412664105

Description:

Job Number:

6.0



Seq. #:

Machine Or Operation:

MS21042L6



Nut

Comment: Qty.:

6.0000 Each(s)/Unit

Total:

6.0000 Each(s)

Nut

Batch:

M101660X

7.0

AN960JD616

Washer



Total:



Comment: Qty.: Washer

I♣ Batch:

18.0000 Each(s)/Unit

Comment: INSPECT 100% KITS FOR COMPLETENESS

18.0000 Each(s)

8.0

QC4



9.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Identify and pack for shipping as per PPP D412-664-105



10.0

QC21



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



N 87-07-16

| D | art | : A | er | os | pac | e | Ltd |
|---|-----|-----|----|----|-----|---|-----|
|---|-----|-----|----|----|-----|---|-----|

| W/O:         |      | WORK ORDER CHANGES     |          |           |     |                                     |                          |  |  |  |
|--------------|------|------------------------|----------|-----------|-----|-------------------------------------|--------------------------|--|--|--|
| DATE         | STEP | PROCEDURE CHANGE       | Ву       | Date      | Qty | Approval<br>Chief Eng /<br>Prod Mgr | Approval<br>QC Inspector |  |  |  |
|              |      |                        |          |           |     |                                     |                          |  |  |  |
| <del> </del> |      |                        |          |           | -   |                                     |                          |  |  |  |
|              |      |                        |          |           |     |                                     |                          |  |  |  |
|              |      |                        |          |           |     |                                     |                          |  |  |  |
| Part No      | ·    | PAR #: Fault Category: | NCR: Yes | No DQ     | A:  | Date:                               |                          |  |  |  |
|              |      |                        | QA:      | N/C Close | d:  | _ Date: _                           |                          |  |  |  |

| NCR: |      | WORK ORDER NON-CONFORMANCE (NCR) |                      |                              |                |              |                       |                         |
|------|------|----------------------------------|----------------------|------------------------------|----------------|--------------|-----------------------|-------------------------|
|      | T    | Description of NC                |                      | Corrective Action Section B  |                | Verification | A                     | <b>A</b>                |
| DATE | STEP | Section A                        | Initial<br>Chief Eng | Action Description Chief Eng | Sign &<br>Date | Section C    | Approval<br>Chief Eng | Approval<br>QC Inspecto |
|      |      |                                  |                      |                              |                |              |                       |                         |
|      |      |                                  |                      |                              |                |              |                       |                         |
|      |      |                                  |                      |                              |                |              |                       |                         |
|      |      |                                  |                      |                              |                |              |                       |                         |
| •    |      |                                  |                      |                              |                | :            |                       |                         |
|      |      |                                  |                      |                              |                |              |                       |                         |
|      |      |                                  |                      |                              |                |              |                       |                         |
|      |      |                                  |                      |                              |                |              |                       |                         |
|      |      |                                  |                      |                              |                |              |                       |                         |

NOTE: Date & initial all entries



|   | DESIG | " P     | DRAWN BY | DART AEROSPACE LTD<br>HAWKESBURY, ONTARIO, CANADA |
|---|-------|---------|----------|---|
| ł | CHEC  | KED #// | APPROVED | DRAWING NO. REV. C                                |
| 1 |       | HA      | All      | D412-664-145 SHEET 1 OF 3                         |
| Ì | DATE  |         |          | TITLE SCALE                                       |
|   | 07.0  | 3.29    |          | CROSSTUBE ASS'Y (412 LOW-N FWD) NTS               |
| I | Α     | i       | 06.12.21 | NEW ISSUE   |
|   | В     |         | 07.03.01 | CHG RUBBER CUSHION                                |
| ľ | С     |         | 07.03.29 | CHG CLAMP & RUBBER CUSHION LGTH.                  |

RELEASED 07.04.240

## PARTS LIST:

| Part Number    | Description   |
|----------------|---|
| D412-664-145   | CROSSTUBE ASSEMBLY (412 LOW-NARROW FWD)   |
| D6019-128      | CROSSTUBE   |
| D2856-250-842  | ABRASION STRIP  |
| D2893-1        | SUPPORT   |
| D3189-3        | CHAFING SHIELD  |
| D3595-063-450  | RUBBER CUSHION  |
| MS21920-24     | CLAMP   |
| MS21920-25     | CLAMP (OR MS21920-26)   |
| MAGNOBOND 6398 | ROCKWELL SPECIFICATION RBO-120-023 ADHESIVE (TEXTRON/BELL SPEC. 299-947-100, TYPE II, CLASS 2 ADHESIVE) |
|                | D412-664-145  D6019-128  D2856-250-842  D2893-1  D3189-3  D3595-063-450  MS21920-24  MS21920-25         |

## **GENERAL NOTES:**

- TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- MATERIAL: MANUFACTURED FROM D6019-128

FINISHED LENGTH = 124.48±0.020 (BEFORE BENDING/TRIMMING)

FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 PRIME INSIDE AND OUTSIDE PER DART QSI 005 4.2


PAINT OUTSIDE PER DART 005 4.2


- 4) PART IS SYMMETRIC ABOUT CENTERLINE, EXCEPT FOR D3189-3 CHAFING SHIELD AND ASSOCIATED HARDWARE
- RUN-OFF PART, BLEND OUT EDGE LONGITUDINALY, TRANSITION SHOULD BE SMOOTH.
- BEND PROGRESSIVELY WITH A MINIMUM OF 8 PASSES. MAXIMUM TUBE FLATTENING DUE TO BENDING IS 6% BASED ON O.D.
- LIQUID PENETRANT INSPECT OUTSIDE SURFACE OF CROSSTUBE PER QSI 038.
- SCRIBE DART PART NUMBER AND BATCH NUMBER IN THIS AREA WITH VIBRATING STYLUS.
- INSTALL D2856-XXX-YYY ABRASION STRIPS WITH A 0.13 (REF) GAP ON BOTTOM SIDE OF CROSSTUBE PER QSI 035.
- 10) EXTREME CARE MUST BE TAKEN TO PROTECT THE OUTSIDE SURFACE OF THE TUBE. THE OUTSIDE SURFACE MUST BE SMOOTH AND FREE FROM SURFACE DEFECTS SUCH AS SCRATCHES, NICKS, OR DENTS. DEFECTS UP TO 0.005" MAY BE BLENDED OUT LONGITUDINALLY. CIRCUMFERENTIAL GRIND MARKS ARE UNACCEPTABLE.
- 11) APPLY A 0.03" TO 0.06" THICK LAYER OF MAGNOBOND 6398 TO THE SURFACE OF D2893-PY THAT WILL BE IN CONTACT WITH THE CROSSTUBE. LET CURE FOR 12 HOURS AFTER TO TO THE SURFACE OF D2893-PY RETURN TO INSTALLATION AND PRIOR TO PACKAGING.
- 12) INSTALL MS21920-25 CLAMPS (OR -26) WITH D3595-063-450 RUBBER CUSHIONS TO SECURE D2893-1 SUPPORT ON TOP SIDE OF THE CROSSTUBE. ENSURE CLAMPS ARE OPPOSITELED COPY CROSSTUBE SUPPORT.

  UNCONTROLLED COPY 13) TORQUE CLAMPS 80 TO 100 IN-LB. ENSURE AT LEAST 1.5 THREADS SHOWING SAFETY OTICE

WITHOUT NOTICE

WORK ORDER NO. 3218





SHOP COPY
RETURN TO
RETURN TO
RETURN TO
REMONERING
ENGINEERING
ENGINEERING
ENGINEERING
UNCONTROLLED COPY
UNCONTROLLED CO

RELEASED 07.04.19

COPPRIGHT © 2008 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

APPROVED

APPROVED

DRAWIN BY

DART

TITLE

CROSSTUBE (412 LOW-NARROW FWD) 1:4